

Time for the second PML "Scratched, Dinged and Dented Sale"!

We occasionally have minor defects in production of our fiberglass nosecones such that they cannot be sold as first-rate items. All cones are structurally sound. All blemishes are to the outer surface coat only. "Soft spots" are very small areas of uncured surface resin due to minor mixing concerns. Sold as-is, all sales are final. E-mail Jerry Kolb at [105571.643@compuserve.com](mailto:105571.643@compuserve.com) or call 1-888-PUBLIC-M for details and shipping charges. You must reference the number of the nosecone when ordering. If you've been looking for a lower-cost fiberglass nosecone but with 99% of the usual PML quality, here's your chance!

+++++

#1 FNC-7.5 small soft spots in surface coat throughout (clean spots, filling and sanding req.) \$55.00

#2 FNC-7.5 crack in surface coat only, near shoulder (fill with med. or thick CA and sand) \$65.00

#3 FNC-7.5 shoulder too tight (major sanding req.) \$60.00

#4 -----sold-----

#5 FNC-7.5 small soft spots in surface coat throughout (clean spots, filling and sanding req.) \$55.00

#6 FNC-11.4 filled chips in surface coat above shoulder (cone made with 1 layer 6oz. cloth, 1 layer 10 oz.) \$160.00

#7 FNC-6.0 lg. chip in surface coat only, near seam midway up (filling and sanding req.) \$60.00

#8 FNC-7.5 small soft spots in surface coat throughout (clean spots, filling and sanding req.) \$55.00

#9 FNC-6.0 lg. chip in surface coat above shoulder (filling and sanding req.); cone slotted 4 slots/9.5" long/0.093 wide, 1 slot goes above shoulder (cone was destined to be a tailcone) \$30.00

#10 FNC-7.5 lg. offset in seam (~0.03" to ~0.05") (cone made with 1 layer 6oz. cloth, 1 layer 10 oz.) (filling and sanding req.) \$50.00

#11 FNC-7.5 lg. offset in seam (~0.03" to ~0.05") (filling and sanding req.) \$50.00

#12 FNC-7.5 lg. offset in seam (~0.03" to ~0.05") (filling and sanding req.) \$50.00