

From: ADW <adwaddell@home.com>
To: ADW <adwaddell@home.com>
Cc: Gerald A. Kolb <105571.643@compuserve.com>; Frank Uroda <75272.1666@compuserve.com>
Subject: PML News: Volume 10
Date: Friday, March 26, 1999 7:05 AM

PML News: Volume 10

Announcing the first PML "Scratched/Dinged/Dented" Sale! Actually, we have a few blemished items that we're selling at reduced prices. Occasionally we have a minor defect in production that we can't sell as "new", but is perfectly functional nonetheless. None of the blemishes affects the item for structural soundness, they're as strong as our regular parts. If you have any questions on these items, please call PML direct at 810-468-1748 9-5pm EST M-F.

- 1) FNC-11.41 nosecone; shoulder above the coupler area had air pocket in surface coat only, has been patched; \$150.00.
- 2) FNC-11.41 nosecone; shoulder above coupler area has cracks in surface coat only; \$140.00.
- 3) FNC-7.5 nosecone; 1/32" offset at parting line. Can be sanded to correct the shape. \$50.00.
- 4) FNC-7.5 nosecone; shoulder OD too large, needs considerable sanding for it to fit airframe but it can be done; \$50.00.
- 5) FNC-6.0 cut and slotted as Bulldog boattail (4 slots, 9.75" long, 0.095 wide, start 5.25" from cut bottom. Tip cut to 3.9" ID). Chipped but patched just above the shoulder. \$50.00.
- 6) FNC-6.0 cut and slotted as Lunar Express boattail (4 slots, call Henry at PML for specs. Tip cut to 2.6" ID). Not a blem or damaged, tip was cut too far, should have been 2.25" ID. \$50.00.

That's it! Again, if you have any questions on these items, please call PML direct at 810-468-1748 9-5pm EST M-F.

Andrew D. Waddell
PML Online Support Rep
TRA 2043 L2/NAR 52875 L2
Email: ADWaddell@home.com
PML: www.publicmissiles.com